

Serial Number: 31-8152194 Registration: N904SC

TTAF: 5645 Hobbs: 3192.2

1981 Piper Chieftain Panther II PA-31-350

ENGINES:	Left Engine:	Right Engine:
Lycoming TIO-540-J2BD	2990.1 Hours Since New	7292.3 Hours Since New
	828.3 Hours Since Overhaul	828.3 Hours Since Overhaul
PROPELLERS:	Left Prop:	Right Prop:
Hartzell HC-C4YR-2	734.9 Hours Since Overhaul (1/2013)	734.9 Hours Since Overhaul (1/2013)
AVIONICS:	Altitude Alert:	Shadin AMS2000
	Audio Panel:	King KMA-24
	Automatic Direction Finder:	King KR-87
	Autopilot/Flight Director:	King KFC-200 w/Yaw Damper
	Communications:	Garmin GNS-530W/King KY-196
	Distance Measuring Equipment:	King KN-63
	ELT:	Artex ELT1000
	Global Positioning System:	Garmin GNS-530W
	Horizontal Situation Indicator:	King KI 525A
	Lightning Detection:	BFG Stormscope
	Moving Map Display:	Avidyne EX-500
	Navigation:	Garmin GNS-530W/King KN-53
	Radar (color):	Bendix RDR-160
	XM Weather:	Garmin GDL 69A
	Traffic:	Avidyne TAS610
	Transponder:	King KT-76A
FEATURES:	Colemill Panther II Conversion	Winglets
	Known Ice	4 Blade Q Tip Props
	BLR Vortex Generators w/GWI	Air Conditioning
	Cargo Door	Shadin Fuel Flow Indicator
	EI Engine Analyzer US-8A	Annual Inspection cw/on 3/22/2018
	American Aviation Intercoolers	Unfeathering Accumulators
	182 Gallon Fuel	Cleveland Wheels and Brakes
INTERIOR:	The Aircraft seating is completed in Light Tan Leather with Desert Sand carpet and coordinating side panels, in an executive style seating arrangement with dual executive writing tables, and a belted rear lav seat. Also featured is a forward beverage center and cabinets, completed in Ribbon Mahogany Laminate. Refurbished January 2013.	
EXTERIOR:	The Aircraft is painted with a Matterhorn White top and Black Velvet Metallic bottom with Burgundy and Gold Metallic accent stripes. New January 2013.	

4801 John Carrell Rd. Denton, Tx. 76207 | 940.484.7555 | Info@nebrig.com | www.nebrig.com