



Serial Number: G-717

Registration: N134CD

TTAF: 5,623 hours

## 1955 Beechcraft T34A Mentor

<b>ENGINE:</b> Continental Motors IO-550-B-9 300Hp	S/N 296772.R 1,220 Hours Since New (1700 hr / 12 year TBO)
<b>PROPELLER:</b> 3-Blade McCauley	1,220 Hours Since New
<b>AVIONICS:</b> ADS-B Compliant (In & Out)	<b>GPS/Comm/Nav:</b> Garmin GTN-650 <b>Autopilot:</b> S-TEC System 60-2 <b>Audio Panel:</b> Garmin GMA-345 <b>Transponder:</b> Garmin GTX-345 <b>Communications:</b> Bendix King KX-165 <b>Navigation:</b> Bendix King KX-165
<b>FEATURES:</b>	Wing Spar AD 2001-13-18 and Center Section AD 2004-25-51 c/w Aug 2007 * Saunders Strap AMOC by Aviadesign Services, Inc. Full Restoration by Parks Industries in 1996 Smoke System Aluminum Control Surfaces Fuel Capacity: 50 gallons (45 gal usable)
<b>INSPECTION:</b>	Annual c/w December 2018 including FAR 91.411 & 413 5yr Wing Spar Eddy Current Inspection December 2018 Wing bolts replaced December 2018



4801 John Carrell Rd. Denton, Tx. 76207 | 940.484.7555 | Info@nebrig.com | www.nebrig.com

Specifications subject to verification upon inspection  
Aircraft subject to availability